

100-PMT 2 and 5 Values PMT 3 and 6 Values Number of Occurances PMT 1 and 4 Values H_{0,0,0} 0 0 0 0 0 0 0 0 H 0,0,Max,P 0 0 Max P 0 110-0 0.2 0.2 0.1 H 0,Max,P,0 Max P 0 0 Max P 0 0 Max P 0 Max P HO, Max P, Max P 0 Max P Max P H Max P.O.O 0 Max P 0 Max P 0 Max P 0 Max P 0 H Max P,0,Max P Max P 0 Max P Max P Max P Max P H Max P. Max P.O 0 Max P H Max P, Max P, Max P Max P Max P Max P

Fig. 4A

4/6




Fig. 4B

